



JPTS75R Instructions



CHARGING

To charge, plug the included cord into the unit and insert into a standard wall outlet (a red led at the bottom will turn on). It takes approximately 6-8 hours to fully charge. Every 2 months, the unit should be charged or sooner if the spark or light becomes noticeably weaker.

HOW TO USE

Make sure the unit is fully charged before first use. When not in use, the Stun On/Off switch on the bottom should be in the OFF position. To use the light, slide the safety switch up to the top position. To use the stun gun, move the Stun On/Off switch on the bottom to the ON position, slide the safety switch down to the bottom position, and press the stun button. Don't test fire for more than three seconds.

WARRANTY

Cutting Edge Products, Inc. extends a Lifetime Warranty to the *JPTS75R* for the product against defects in materials or workmanship, with the following exceptions:



- The warranty does not cover damage resulting from accident, misuse or abuse, lack of reasonable care, moisture, the affixing of any attachment not provided with the product, loss of parts, or recharging the unit in any manner not in accordance with the included instructions.
- The warranty will be voided if the unit has been opened or tampered with in any way (unless by an Authorized Dealer) or if any unauthorized replacement parts have been used.
- The Lifetime Warranty covers the stun gun only. The holster and the lanyard attached to the disable pin are excluded.

TO OBTAIN SERVICE

Contact the Authorized Dealer from whom you purchased this unit for a Return Merchandise Authorization. The return unit must be sent postage prepaid and proof of purchase is required. Damage or loss occurring during shipment is not covered by this warranty.